

Water Testing Report Perform by SSE/W/WS/LMG with medical Department

Date :- 07.04.23

Location	Residual Chlorine	Ph. Value	Turbidity	Iron Test	TDS	Bacteria
Acceptable limit	0.2ppm	6.5-8.5	5.0 NTU	0.3ppm	500	Test perform By Medical Department
At Station(Surface Water)	0.20	7.00	3.0	0.04	300	
At Filter House (Surface Water)	0.2	7.50	3.0	0.02	310	
At Hospital (surface Water)	0.2	7.10	4.0	0.03	300	
Deep tube well						
At Hospital	0.2	6.80	1.0	0.02	290	
At Station	0.2	6.90	2.50	0.02	220	
At DTS Hill Colony	0.2	7.00	2.0	0.02	250	
At A/C Colony	0.2	7.30	2.0	0.05	230	
At master colony	0.2	7.20	1.0	0.06	280	
At New Colony	0.2	7.00	1.0	0.07	300	
Front of Employees Union office	0.2	7.00	1.50	0.09	320	
At RPSF colony	0.2	6.80	2.0	0.04	200	

07.04.23.  
 Health & P.  
 Health & P.

07.04.23.  
 Health & Material Inspector/Grade -  
 N F Rly Ludhiana

07.04.23.  
 Senior Section Engineer (Work  
 Water Supply, LMG, N F Rai